

**Date:** December 26<sup>th</sup>, 2006

**Number:** TAB 06-008

**To:** Distribution, Global

## FSA-210, FSA-410 and FSB-210 Field Replacement Program

This is to inform you of a potential issue regarding the FSA-210, FSA-410 and FSB-210 smoke detectors (all models) manufactured between October 30<sup>th</sup>, 2006 and December 15<sup>th</sup>, 2006. Under certain conditions, the resonator component could fail to function as normal, and cause the detector to fail to detect smoke reliably.

Effective immediately, please return all FSA-210, FSA-410 and FSB-210 inventory manufactured between October 30<sup>th</sup>, 2006 and December 15<sup>th</sup>, 2006 for replacement.

The date code of manufacture is clearly printed on a white sticker located on the back of the unit.

All products manufactured before October 30<sup>th</sup>, 2006 and on or after December 15<sup>th</sup>, 2006 are not affected. You will receive a follow-up communication soon regarding what to do with installed product that falls within this date range.

We apologize for any inconvenience this may have caused.

Please contact the DSC Customer Help Center at 905-760-3000, or send an email to [info@dsc.com](mailto:info@dsc.com) or [tech@dsc.com](mailto:tech@dsc.com) if you have any questions.

**Harry Scholz**  
**Manager, Customer Help Center**

**905-760-3000 ext. 2441**  
[hscholz@dsc.com](mailto:hscholz@dsc.com)