

Date: December 26th, 2006

Number: TAB 06-008

To: Distribution, Global

FSA-210 and FSA-410 Field Replacement Program

This is to inform you of a potential issue regarding the FSA-210 and FSA-410 smoke detectors manufactured between October 30th, 2006 and December 15th, 2006. Under certain conditions, the resonator component could fail to function as normal, and cause the detector to fail to detect smoke reliably.

Effective immediately, please return all FSA-210 and FSA-410 inventory manufactured between October 30th, 2006 and December 15th, 2006 for replacement.

The date code of manufacture is clearly printed on a white sticker located on the back of the unit.

All products manufactured before October 30, 2006 and on or after December 26th, 2006 are not affected. You will receive a follow-up communication soon regarding what to do with installed product that falls within this date range.

We apologize for any inconvenience this may have caused.

Please contact the DSC Customer Help Center at 905-760-3000, or send an email to info@dsc.com or tech@dsc.com if you have any questions.

Harry Scholz
Manager, Customer Help Center

905-760-3000 ext. 2441
hscholz@dsc.com