

Date: Thursday, July 24, 2008

Number: TAB-08-008

To: North American Sales Channel

Notice: GS3060 Phone Line Wiring

We would like to inform you of a possible wiring issue regarding the GS3060 product.

In applications where the GS3060 is wired as a backup communicator, the unit may answer incoming calls if the TIP and RING wires are reversed at the GS3060.

To correct this, simply swap the TIP and RING wires going into the GS3060 terminal block.

Please contact the DSC Customer Help Center at 905-760-3000, or send an email to info@dsc.com or tech@dsc.com if you have any questions.

Communications

To order, call +1-905-760-3000.
For more information on these or other DSC products, e-mail info@dsc.com
or contact your DSC Inside Sales Representative.