



## Discontinuation Notice

# PowerSeries Wireless Receiver Kit RF5132WKK1-433

**Date:** October 19, 2020  
**Region:** NA, LATAM, APAC  
**Product:** RF5132WKK1-433  
**Brand:** DSC



### Scope

The PowerSeries Wireless Receiver Kit, which includes the 433 MHz Wireless Receiver and the 4-Button Key Fob, has been discontinued effective immediately. The 433 MHz Wireless Receiver and the 4-Button Key Fob are available to be purchased separately.

### Affected Products

Part Number	Description	Replacement Part Number	Replacement Description
RF5132WKK1-433	PowerSeries Wireless Receiver with Key fob	RF5132-433(W) & WS4939	PowerSeries Wireless Receiver & 4-Button Wireless Key

Note: Due to material availability, orders significantly higher than forecast or historical run rate may not be accepted.

## Contact Information

<b>Order Entry</b>	1-888-888-7838
<b>Sales</b>	Contact your local sales rep. or email <a href="mailto:info@dsc.com">info@dsc.com</a>
<b>Technical Support</b>	North America: +1-800-387-3630 Latin America: +1-416-645-8083 <u>APAC Local Direct Dial Numbers:</u> India: +91-80-4199-0994 China: +86-21-6163-8644 Australia: +61-28-317-1322 Oceania and New Zealand: +64-9942-4004  <u>APAC Local Toll-Free Numbers:</u> Australia: 1-800-580-946 China: 400-6711-528  or email: <a href="mailto:intrusion-support@jci.com">intrusion-support@jci.com</a>
<b>Product Manager</b>	Nav Dhillon <a href="mailto:navjot.dhillon@jci.com">navjot.dhillon@jci.com</a>



Johnson Controls

5757 N. Green Bay Avenue | P.O. Box 591 Milwaukee, WI 53201 | 441-524-1200