

New Product Announcement

Date: October 15, 2018
Region: North America
Product: PowerSeries Neo firmware update
Brand: DSC



Profile

We are pleased to announce the release of new firmware for PowerSeries Neo which improves the overall system performance and security. The new release includes feature enhancements, functionality improvements and a second type of ITV2 encryption. All updates are listed below.

To support the new functionality, upgrading of the Panel (v1.33), communicator (v5.3) and keypad (v1.33) is required. New V1.33 drivers for DLS 5 will also be available and can be installed from the Help menu in DLS 5 by navigating to **“Help – Updates – Check for Web Updates”**.

Features, Benefits & Value

Feature	Benefit	Value
Type 2 Encryption	New command allows session key to be dynamically changed	Added security within integration protocol
Visual Verification performance improvements	General improvements to optimize performance of image transmissions to the central station receiver	Reduce false dispatches with verified visual images
Communication path reporting	Established unique reporting codes to differentiate between cellular and Ethernet path failure	Enhances ability to remotely identify the cause of failure at the premises

Availability

- Available now for upgrading local or remote via DLS5
- New production with these firmware versions will begin shortly

New Reporting Codes

System Event	Contact ID		SIA	
	Previous Report Code	New Report Code	Previous Report Code	New Report Code
Alternate Communicator Radio/SIM Failure	E3AA-001	E3AA-991	YX-0001	YX-0991
Alternate Communicator Radio/SIM Failure Restore	R3AA-001	R3AA-991	YZ-0001	YZ-0991
Alternate Communicator GSM Network Fault	E3AA-001	E3AA-992	YX-0001	YX-0992
Alternate Communicator GSM Network Fault Restore	R3AA-001	R3AA-992	YZ-0001	YZ-0992
Alternate Communicator Ethernet Trouble	E3AA-001	E3AA-993	YX-0001	YX-0993
Alternate Communicator Ethernet Trouble Restore	R3AA-001	R3AA-993	YZ-0001	YZ-0993
Alternate Communicator SIM Lock Trouble	E3AA-001	E3AA-994	YX-0001	YX-0994
Alternate Communicator SIM Lock Trouble Restore	R3AA-001	R3AA-994	YZ-0001	YZ-0994
Alternate Communicator SMS Config. Trouble	E3AA-001	E3AA-995	YX-0001	YX-0995
Alternate Communicator SMS Config. Restore	R3AA-001	R3AA-995	YZ-0001	YZ-0995

Pricing & Ordering Information

Pricing and ordering remains the same. There are no new part numbers.

Contact Information

Order Entry	Sales	Technical Support	Product Manager
1-888-888-7838	Contact your local sales rep. or email info@dsc.com	North America: +1-800-387-3630 or email: Intrusion-support@tycoint.com	Beth Krpan beth.krpan@jci.com