

**Date:** Monday, February 28, 2005

**Number:** TAB 05-001

**To:** Global Distributors

## Escort5580 Automation Output Control Issue

This is to inform you of an issue regarding the Escort5580 product related to automation output control. The option to have the Escort5580 activate an automation output based on PGM and schedule is not available.

Programming an automation item to follow a PGM output only or programming an automation item to follow a schedule only is the recommended usage.

This affects all versions of the Escort5580, including the 'TC' versions.

Please contact the DSC Customer Help Center at 888-888-7838 or [info@dsc.com](mailto:info@dsc.com) or contact DSC Technical Support at 800-387-3630 or [tech@dsc.com](mailto:tech@dsc.com) if you have any questions.

**Harry Scholz**  
**Manager, Customer Help Center**

**905-760-3000 ext. 2441**  
[hscholz@dsc.com](mailto:hscholz@dsc.com)