

Technical Advisory Bulletin

Date: November 6, 2006 **Number:** TAB 06-006

To: Distribution, North America, Latin America, Mexico and New Zealand

RF5132 version 5.0 Tamper

DSC would like to inform you of a possible issue regarding the RF5132 version 5.0 wireless receivers regarding the new case and wall tamper options.

Several units have been shipped with the case and wall tamper options enabled. If enabled, the control panel will display a General System Tamper trouble.

To disable the case and wall tamper options in the RF5132 version 5.0 wireless receiver:

- Enter [*][8][Installers Programming] to enter Installers Programming
- Enter Section [804] to enter Wireless Receiver Programming
- Enter Section [90] and turn ON Options [3] and [4] to disable the tampers

We apologize for any inconvenience this may cause.

Please contact the DSC Customer Help Center at 905-760-3000, or send an email to info@dsc.com or tech@dsc.com if you have any questions.

Harry Scholz Manager, Customer Help Center

905-760-3000 ext. 2441 hscholz@dsc.com