

Date: December 22nd, 2008

TAB Number: 08-012

To: U.S. Distributors

Notice: PK/RFK55XX Keypads

We would like to inform you of a cosmetic issue regarding version 1.11 of the PK/RFK5501, PK/RFK5508 & PK/RFK5516 keypads.

When the system is disarmed after an alarm the keypad will 'pause' for up to 10 seconds. After this time the keypad will return to normal operation. On the PK/RFK5501 keypad the clock display will be updated within 4 minutes.

Version 1.12 has been released to correct this issue.

Please note that this issue does not affect the PK/RFK5500 keypads.