

Intertek House, Cleeve Road, Leatherhead, Surrey, KT22 7SB, United Kingdom

Phone: +44 (0) 1372 370900 E-mail: certificates@intertek.com

CERTIFICATE

No. 000067 / 03

In accordance with the **CertAlarm** Rules and Certification System 5, as defined in ISO / IEC Guide 67, we certify that the product

WT4989/8989 - Wireless fob

is in conformity with the following standard(s)

EN50131-3:2009

Control and indicating equipment

EN50131-5-3:2005 + A1:2008

Interconnections equipment using radio frequency techniques

Digital Security Controls (DSC) a division of Tyco Safety Products Canada

3301 Langstaff Road, L4K 4L2 Concord, Ontario, CANADA

is authorised to use the CERTALARM Mark on the above mentioned product

This certificate is valid until:

10th May 2021

Signed on behalf of Intertek Testing & Certification Limited.

10th May 2017

Billy Blakeman Certification Officer CERTALARM
the Quality Mark
for Fire
& Security





Intertek House, Cleeve Road, Leatherhead, Surrey, KT22 7SB, United Kingdom

Phone: +44 (0) 1372 370900 E-mail: certificates@intertek.com

CERTIFICATE

No: 000067 / 03 - Annex No 1

Job Reference: LSS 0210

Takes into account the following products:

WT4989/8989 - Wireless fob

The optional features of the specifications that are included in the product and test report:

Security grade: 2

Environmental class: II

Equipment class: Portable

Power supply Type C

Intended for use in the Alexor system

This approval does not cover use with fire and auxiliary alarm features initiated

Test Report Numbers:

Alexor EN50130-4 Telefication Rpt 20114082800rev3.0

Alexor SP Test report PX14283A rev2

PC9155-433 EN50131-5-3 Telef Rpt 20103536800rev 1

PC9155 EN50131 SP Test report PX04186A

PC9155D-433 &acc EN50130-5 (M) Class 2 SP TR PX01099A r2

PT4_WT4989 Water Ingress Test report PX01099D

WT4989 Telefication Certificate 11229052 AA00





Intertek House, Cleeve Road, Leatherhead, Surrey, KT22 7SB, United Kingdom

Phone: +44 (0) 1372 370900 E-mail: certificates@intertek.com

CERTIFICATE

No: 000067 / 03 - Annex No 2

Documents submitted;

General assembly drawing 75000055_WT4989	Issue B/0
WT4989(Ua561_Rev02)_sch	Issue 02
WT4989(UA561 REV02)_parts list	Issue 02 (003)
WT4989 (UA561_rev02) _pcb_11002999	Issue 02
WT4989 (UA561_rev02) _pcb_11002999	Issue 02
WT4 <mark>989 (</mark> UA561_rev02) _pcb_11002999 n	Issue 02
WT49 <mark>89 m</mark> echanical assembly_ door assembly	Issue A/3
WT4989 mechanical dwg_back	Issue B/0
WT4989 mechnical assembly_clip assembly	Issue A/0
WT4989 mechnical assembly_front assembly	Issue D/0
WT4989 mechnical dwg_ front	Issue B/3
WT4989 mechnical dwg_carrier	Issue A/6
WT4989 mechnical dwg_door	Issue B/1
WT4989 Label 18008288R007	Issue n/a
WT4989 Installation Manual 29007536R007	Issue 007





Intertek House, Cleeve Road, Leatherhead, Surrey, KT22 7SB, United Kingdom

Phone: +44 (0) 1372 370900 E-mail: certificates@intertek.com

CERTIFICATE

No: 000067 / 03 - Annex No 3

Validity of Certificate:

The Certificate remains valid based upon satisfactory annual factory production control audits and follow up re-testing as required by CertAlarm scheme rules.

DISCLAIMER

This Certificate is for the exclusive use of Intertek's Client and is provided pursuant to the Certification agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this certificate. Only the Client is authorized to permit copying or distribution of this certificate and then only in its entirety. Use of the CertAlarm Certification mark is restricted to the conditions laid out in the agreement. Any further use of the Intertek name for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. Initial Factory Assessments and Follow up Services are for the purpose of assuring appropriate usage of the Certification mark in accordance with the agreement, they are not for the purposes of production quality control and do not relieve the Client of their obligations in this respect

