

Product Battery Quick Reference Guide International

2-Way Wireless Products

Product	Product Type	Battery Type	Notes	Quantity
IMPASSA (9055)	Self Contained Wireless Panel	7.2V, 1500MAH Ni-MH or 7.2V, 3600MAH Ni-MH	DSC - "SCW-BATTERY" or DSC - "SCW-BATTERYHC"	1
ALEXOR (PC9155)	2-Way Wireless Panel	12V, 2.3AH Sealed Lead Acid	DSC - "BD2.3-12"	1
WT5500	2-Way Wireless Keypad	1.5V Alkaline, AA	Energizer	4
WT4989/WT8989	2-Way Wireless Key	3V Lithium, CR2032	Panasonic, Energizer	2
WT4901/WT8901	2-Way Wireless Siren	1.5V Alkaline, AA	Energizer	4
WT4911/WT8911	2-Way Wireless Siren	3.6V D-SIZE, 14AH LI-THIONYL CHLORIDE	DSC - "WT4911BATAM-80PK" or DSC - "WT4911BATAM-20PK"	1

1-Way Wireless Products

Product	Product Type	Battery Type	Notes	Quantity
PowerSeries 9045/9047	Self Contained Wireless Panel	7.2V, 1500MAH Ni-MH	DSC - SCW-BATTERY	1
WS4920/WS8920	1-Way Wireless Repeater	4.8V, 2100MAH Ni-MH	DSC - "WS4920BATT-8PK"	1
WS4938W/WS8938W	Wireless Panic	3V Lithium, CR2025	Panasonic	2
WS4938-2W	Wireless Panic	3V Lithium, CR2025	Panasonic	2
WS4939EU/WS8939W	Wireless Key	3V Lithium, CR2025	Panasonic	2
WS4945W/WS8945W	Wireless Door/Window Contact	3V Lithium, CR2	Duracell, Panasonic	1
WS4975W/WS8975W	Wireless Door/Window Contact	3V Lithium, CR2032	Panasonic	1
WS4904PW/WS8904PW	Wireless Motion Detector	3V Lithium, CR123A	Energizer, Panasonic, Duracell	1
WS4904PW/WS8904PW	Wireless Motion Detector	3V Lithium, CR123A	Energizer, Panasonic, Duracell	1
WS4913EU/WS8913EU	Wireless Carbon Monoxide Detector	3V Lithium, CR123A	Duracell	1
WS4916EU/WS8916W	Wireless Smoke Detector	3V Lithium, CR123A	Panasonic, Sanyo, Duracell	2
WS4985W/WS8985W	Wireless Flood Detector	3V Lithium, CR2	Duracell, Panasonic	1
WS8965W	Wireless Door/Window Contact	3V Lithium, CR123A	Panasonic	1
WLS912L-433W	Wireless Glassbreak Detector	3V Lithium, CR123A	Energizer, Panasonic, Duracell	2

DSC's products are designed to work with specific batteries to ensure maximum performance and reliability of each product. Substitutions or using batteries other than the above recommendations could result in malfunctions and/or warranty issues.